


ISSUE NO. : 13-09	DATE : June. 19th. 2013	PAGES : 1 OF 1
-------------------	-------------------------	----------------

SUBJECT	Quality improvement of Horn Assy
MODEL	All models
EFFECTIVE F/M NO	Refer to below information

PURPOSE	Quality improvement
----------------	---------------------

DETAIL	<p>-To prevent screw loosening and water penetration, we are adding more control for ① tightening the screw at the stay part and ② spreading epoxy on two rivets and adjust screws</p> 
---------------	---

EFFECTIVE VIN. NO.				
	Part no.	Model	Effective Vin.no.	
	38500HP9510	GV700	KM4VR51A3D1501090	2013-04-08
		GV650P	KM4VP61A1D1100116	2013-04-15
		GV650	KM4VP62A8D1500477	2013-05-16
		GT650	KM4MP62D9D1500476	2013-04-11
		GT250	KM4MJ627XD1700391	2013-04-03
		GT125	KM4MF55BXD1501952	2013-04-18
RT125		KM4SF42A3D1503099	2013-04-17	
		Production Date		